Photo 1. Protection of Elderberry Shrub South of Uncontrolled Fill Area

Photo 2. Start of Excavation for Test Pit TPB-1 in Main Landfill Area

Photo 3. Test Pit TPB-1 in Main Landfill Area

Photo 4. Segregated Stockpiles From Test Pit TPB-1 Being Placed on Plastic Sheeting

Photo 5. Fill Material From Test Pit TPB-1 in Main Landfill Area

Photo 6. Backfilling of Test Pit TPB-1

Photo 7. Compaction of Backfill Using Backhoe and Sheepsfoot Attachment